



# Irwell Catchment Pilot waterbodies failing for physical modification



**Flood defence - structures**



**Urbanisation - other**



**Artificial / Heavily Modified Waterbodies**

- - - - A / HMWB

**River ecological classification**


- High
- Good
- Moderate
- Poor
- Bad

**Physical Modification**


**Urbanisation - other**

- Low
- High

**Barriers to fish migration**



**Water level management**



**Flood defence - structures**

- Low
- High

**Water level management**

- Medium

**Fish barriers**

- Low
- High

